

```

<table border="0" width="550"><tr><td rowspan="1"> </td><td scope="" style="width: 0px;"
dir="" id="" align="" valign="" lang=""> </td><td align="right"> <br /></td></tr><tr><td
rowspan="1"> </td><td> </td><td> </td></tr><tr><td scope="" style="width: 130px;" dir="" id=""
colspan="1" align="center" valign="top" lang=""> </td><td scope="" style=""
dir="" id="" colspan="1" align="left" valign="top" lang=""><table bordercolorlight="#99b7d1"
bordercolordark="#ffffff" align="center" bgcolor="#ffffff" border="1" cellpadding="2"
cellspacing="0" width="140"><tr><td>Section</td> <td>~b<br />mm</td> <td>~h<br
/>mm</td> <td>angle<br />◊</td> </tr> <tr> <td>HL</td>
<td>45</td> <td>20</td> <td>28</td> </tr> <tr> <td>H◊</td>
<td>50</td> <td>22</td> <td>28</td> </tr> <tr> <td>H36</td>
<td>36</td> <td>14</td> <td>28</td></tr></table><p> Orders as per length Lw.
</p></td><td scope="" style="" dir="" id="" colspan="1" align="left" valign="top" lang=""><table
bordercolorlight="#99b7d1" bordercolordark="#ffffff" bgcolor="#ffffff" border="1" cellpadding="2"
cellspacing="0" width="200"><tr><td>Section</td> <td>Range of Lw lengths</td>
</tr> <tr> <td>HL (45x20)</td> <td>2240 - 5000</td> </tr> <tr>
<td>HL (45x20) Ravlek</td> <td>2800 - 5000</td> </tr> <tr> <td>HM
(50x22)</td> <td>2000 - 5000</td> </tr> <tr> <td>HM (55x22)
Ravlek</td> <td>2800 - 5000</td> </tr> <tr> <td>H36</td>
<td>1120 - 2240</td></tr></table> </td></tr><tr><td colspan="1"> </td><td
colspan="1"> </td><td colspan="1"> </td><td colspan="3"> The listed
lengths are only recommended. Any length is available in the mentioned
range.</td></tr><tr><td colspan="1"> </td><td colspan="1"> </td><td
colspan="1"> </td><td colspan="1" align="center"
valign="top" lang=""><table bordercolorlight="#99b7d1" bordercolordark="#ffffff" align="center"
bgcolor="#ffffff" border="1" cellpadding="2" cellspacing="0" width="160"><tr><td colspan="2"
class="HEAD">HL</td> </tr> <tr align="center"> <td class="HEAD"
width="80">Lw<br />mm</td> <td class="HEAD" width="80">Li<br />mm</td> </tr>
<tr> <td>2240</td> <td>2160</td>
</tr> <tr> <td>2300</td> <td>2220</td>
</tr> <tr> <td>2360</td>
</tr> <tr> <td>2430</td>
</tr> <tr> <td>2500</td> <td>2420</td> </tr> <tr>
<td>2580</td> <td>2500</td> </tr>
<tr> <td>2650</td> <td>2570</td> </tr>
<tr> <td>2720</td> <td>2640</td>
</tr> <tr> <td>2800</td> <td>2720</td>
</tr> <tr> <td>2900</td>
</tr> <tr> <td>2820</td> <td>2900</td>
</tr> <tr> <td>3000</td>
</tr> <tr> <td>2920</td> <td>3000</td>
</tr> <tr> <td>3070</td> <td>2990</td>
</tr> <tr> <td>3150</td> <td>3070</td>
</tr> <tr> <td>3250</td> <td>3170</td>
</tr>

```

	<tr>	<td>3350</td>	<td>3270</td>								
</tr>	<tr>	<td>3450</td>	<td>3370</td>								
</tr>	<tr>	<td>3550</td>									
<td>3470</td>	</tr>	<tr>	<td>3650</td>								
<td>3570</td>	</tr>	<tr>									
<td>3750</td>	<td>3670</td>	</tr>	</tr>	<tr>							
<td>3870</td>	<td>3790</td>	</tr>	</tr>	</tr>							
<tr>	<td>4000</td>	<td>3920</td>	</tr>	</tr>							
<tr>	<td>5000</td>										
<td>4920</td>	</tr>	</table>	</td>	<td colspan="1"><table bordercolorlight="#99b7d1" bordercolordark="#ffffff" align="center" bgcolor="#ffffff" border="1" cellpadding="1" cellspacing="0" width="160"><tr><td colspan="2" class="HEAD">HM</td>	</tr>	<tr align="center">	<td class="HEAD" width="80">Lw mm</td>	<td class="HEAD" width="80">Li mm</td>	</tr>	<td>2000 </td>	
</td>	<td>1910</td>	</tr>	<tr>	</tr>	<td>2240						
<td>2300 </td>	<td>2150</td>	</tr>	<tr>	</tr>	<td>2210</td>		</tr>	<tr>			
<td>2360 </td>	<td>2270</td>	</tr>	<tr>	</tr>	<td>2430 </td>		<td>2340</td>	</tr>			
<tr>	<td>2500 </td>	<td>2410</td>	</tr>	</tr>	<td>2580 </td>		<td>2490</td>	</tr>			
</tr>	<tr>	<td>2650 </td>	</tr>	</tr>	<td>2720 </td>		<td>2800				
<td>2560</td>	</tr>	<tr>	<td>2630</td>	</tr>	<tr>		<td>2710</td>	</tr>			
<td>2900 </td>	<td>2810</td>	</tr>	<tr>	</tr>	<td>3000 </td>		<td>2910</td>	</tr>			
<tr>	<td>3070 </td>	<td>2980</td>	</tr>	</tr>	<td>3150 </td>		<td>3060</td>	</tr>			
</tr>	<tr>	<td>3250 </td>	<td>3160</td>	</tr>	<tr>		<td>3350 </td>	</tr>			
<td>3260</td>	</tr>	<tr>	<td>3360</td>	</tr>	<tr>		<td>3450 </td>	</tr>			
</td>	<td>3460</td>	</tr>	<tr>	</tr>	<td>3560</td>		<td>3660</td>	</tr>			
<td>3650 </td>	<td>3750 </td>	<td>3780</td>	</tr>	</tr>	<td>3870 </td>		<td>3910</td>	</tr>			
<tr>	<tr>	<td>4000 </td>	<td>4030</td>	</tr>	<tr>		<td>4120 </td>	</tr>			
</tr>	<tr>	<td>4250 </td>	</tr>	</tr>	<td>4160</td>		<td>4370 </td>	</tr>			
</td>	<td>4280</td>	</tr>	<tr>	</tr>	<td>4410</td>		<td>4500				
</td>	<td>4410</td>	</tr>	<tr>	</tr>	<td>4620 </td>		<td>4530</td>	</tr>			
<td>4620 </td>	<td>4750 </td>	<td>4660</td>	</tr>	</tr>	<td>4870 </td>		<td>4780</td>	</tr>			
<tr>	<td>4870 </td>	<td>4780</td>	</tr>	</tr>	</tr>		</tr>	</tr>			

```

        <tr>                <td>5000 </td>
<td>4910</td></tr></table> </td><td scope="" style="" dir="" id="" colspan="1" align="center"
valign="top" lang=""><table bordercolorlight="#99b7d1" bordercolordark="#ffffff" align="center"
bgcolor="#ffffff" border="1" cellpadding="2" cellspacing="0" width="90"><tr><td colspan="2"
class="HEAD">H36</td>    </tr>    <tr>    <td class="HEAD" align="center"
width="90">Lw<br />mm</td>    </tr>    <tr>    <td>1120</td>    </tr>    <tr>
<td>1180</td>    </tr>    <tr>    <td>1206</td>    </tr>    <tr>    <td>1220</td>    </tr>
<tr>    <td>1250</td>    </tr>    <tr>    <td>1280</td>    </tr>    <tr>    <td>1320</td>
</tr>    <tr>    <td>1360</td>    </tr>    <tr>    <td>1400</td>    </tr>    <tr>
<td>1450</td>    </tr>    <tr>    <td>1500</td>    </tr>    <tr>    <td>1550</td>    </tr>
<tr>    <td>1600</td>    </tr>    <tr>    <td>1650</td>    </tr>    <tr>    <td>1700</td>
</tr>    <tr>    <td>1750</td>    </tr>    <tr>    <td>1786</td>    </tr>    <tr>
<td>1800</td>    </tr>    <tr>    <td>1850</td>    </tr>    <tr>    <td>1900</td>    </tr>
<tr>    <td>1950</td>    </tr>    <tr>    <td>2000</td>    </tr>    <tr>    <td>2060</td>
</tr>    <tr>    <td>2120</td>    </tr>    <tr>    <td>2180</td>    </tr>    <tr>
<td>2240</td></tr></table> </td></tr><tr><td colspan="1"> Lw = Li + 80</td><td
colspan="1"> Lw = Li + 90</td><td colspan="1"> Lw = Li - 66</td></tr><tr><td
colspan="1"> </td><td colspan="1"> </td><td colspan="1"> </td></tr><tr align="center"><td
rowspan="1" colspan="3"> Belts are resistant to temperatures from -30 ◊C to +60 ◊C at
relative humidity 65+/-15%.</td></tr><tr><td rowspan="1" colspan="3"><hr size="2"
width="100%"></td></tr><tr><td colspan="1" align="center">Example of marking:<br /><br
/><b> HL 2300Lw 2220Li</b><br /><br />HL - marking of section<br />Lw - pitch length<br />Li
- inside length <br /></td><td colspan="1" align="center"> </td><td colspan="1"
align="center"> Example of marking:<br /><br /><b> H36 1400Lw</b><br /><br />H36 -
marking of section<br />Lw - pitch length</td></tr></table>

```