

```

<table border="0" width="550"><tr><td scope="" style="width: 150px;" dir="" id="" align="center"
valign="" lang=""> </td><td rowspan="1"> </td><td rowspan="1"> </td><td align="right"> <br /></td></tr><tr><td scope=""
style="width: 150px;" dir="" id="" align="left" valign="top" lang=""> </td><td scope="" style="" dir="" id=""
rowspan="1" align="left" valign="top" lang=""><table bordercolorlight="#99b7d1"
bordercolordark="#ffffff" bgcolor="#ffffff" border="1" cellpadding="2" cellspacing="0"
width="140"><tr><td>Section</td> <td>~b<br />mm</td> <td>~h<br />mm</td>
</tr> <tr> <td>PJ</td> <td>28</td> <td>14</td> </tr> <tr>
<td>PK</td> <td>30</td> <td>14</td> </tr> </table> <br
/></td><td rowspan="1"> </td><td </td></tr><tr><td colspan="1"> </td><td
colspan="1"> </td><td colspan="1"> </td></tr><tr><td rowspan="1"
colspan="2">Orders as per length Le.<br />Maximum number of ribs for PJ section = 18<br
/>Maximum number of ribs for PK section = 12</td><td colspan="1"> </td><td
colspan="1"> </td></tr><tr><td scope="" style="" dir="" id="" colspan="1" align="left"
valign="top" lang=""><table bordercolorlight="#99b7d1" bordercolordark="#ffffff" align="center"
bgcolor="#ffffff" border="1" cellpadding="2" cellspacing="0" width="80"><tr><td
class="HEAD"><b>PJ</b></td> </tr> <tr align="center"> <td class="HEAD"
width="80"><b>Le<br />mm</b></td> </tr> <tr> <td>560</td>
</tr> <tr> <td>630</td> </tr> <tr> <td>655</td> </tr>
<tr> <td>705</td> </tr> <tr> <td>742</td> </tr> <tr> <td>770</td> </tr>
<tr> <td>805</td> </tr> <tr> <td>830</td> </tr> <tr> <td>850</td> </tr>
<tr> <td>853</td> </tr> <tr> <td>860</td> </tr> <tr> <td>880</td> </tr>
<tr> <td>890</td> </tr> <tr> <td>900</td> </tr> <tr> <td>910</td> </tr>
<tr> <td>920</td> </tr> <tr> <td>930</td> </tr> <tr> <td>940</td> </tr>
<tr> <td>950</td> </tr> <tr> <td>960</td> </tr> <tr> <td>970</td> </tr>
<tr> <td>980</td> </tr> <tr> <td>990</td> </tr> <tr> <td>1000</td> </tr>
<tr> <td>1010</td> </tr></table></td><td scope="" style="" dir="" id="" colspan="1" align="left"
valign="top" lang=""><table bordercolorlight="#99b7d1" bordercolordark="#ffffff" align="center"
bgcolor="#ffffff" border="1" cellpadding="2" cellspacing="0" width="80"><tr><td
class="HEAD"><b>PJ</b></td> </tr> <tr align="center"> <td class="HEAD"
width="80"><b>Le<br />mm</b></td> </tr> <tr> <td>1020
</td> </tr> <tr> <td>1050 </td> </tr> <tr> <td>1055 </td> </tr>
<tr> <td>1060 </td> </tr> <tr> <td>1065 </td> </tr> <tr> <td>1070 </td>
</tr> <tr> <td>1160 </td> </tr> <tr> <td>1163 </td> </tr>
<tr> <td>1165 </td> </tr> <tr> <td>1175 </td> </tr>
<tr> <td>1180 </td> </tr></table></td></tr></table>

```

		1230	
	1235		
1301			1309
		1372	
	1375		
1380			

  

<b>PK</b>			
Le mm			
		630	
		650	
	698		
700			736
		737	
	740		742
		800	
	812		
847			850
		853	
	950		954
		968	
	970		
975			980
		985	

  

<b>PK</b>			
Le mm			
	1005		
1015			1045
		1050	
	1054		
1060			1070
		1150	
	1152		
1163			1165
		1170	
	1180		
1220			1225
		1230	
	1300		
1365			
1370			

Belts are resistant to temperatures from -45 °C to +80 °C.  
Increased resistance to mineral oils.  
Increased resistance to abrasion.

---

Example of

marking: **4PK 954**  
4 - number of ribs  
PK - marking of section  
954 - effective length